

Axel remote telemetry

MWD operations from the office for cost optimization

Typical MWD field crew




MWD Field engineers work shifts

Tasks

Stage	Time	% of total value
1. Cluster preparation	4h	1.6%
2. MWD assembly and configuration	5h	2,08%
3. BHA assembly and ToolFace Offset measurement	6h	2.5%
4. Pre-drilling checks	1h	0.42%
5. BHA running	16h	6.67%
6. Pipe drilling 7. Taking measurements and reporting	196h	81.67%
8. Completion of work after reaching drilled depth	12h	5%

Stage requiring optimization

Remote MWD engineer



Each MWD crew can be reduced from 2 to 1 MWD engineers.
MWD Engineer can support up to 6 wells from the office.

What can a remote MWD engineer do?




Drilling mode control



Decoding control



Measurement control, relogging



Work with data and report generation

Contacts

Axelmwd.ru
+7 (499) 147- 27-50
Artem.Budagyan@axelmwd.com